





HL80.2H

0,50 l/sec
DN50/75



9 003076 701827



D BODENABLAUF
I SCARICO A PAVIMENTO
GB FLOOR DRAIN

TR YER SÜZGEÇİ
CZ/SK PODLAHOVÁ VPUST
HR PODNI ODVOD




H PADLÓLEFOLYÓ
PL WPUST PODLOGOWY
SLO TALNI ODTOK

RO SIFON DE PARDOSEALĂ
PYC ТРАП
BUL ПОДОВ СИФОН


03.05.2016

HL80.2H

0,50 l/sec
DN50/75



9 003076 701827



D BODENABLAUF
I SCARICO A PAVIMENTO
GB FLOOR DRAIN

TR YER SÜZGEÇİ
CZ/SK PODLAHOVÁ VPUST
HR PODNI ODVOD




H PADLÓLEFOLYÓ
PL WPUST PODLOGOWY
SLO TALNI ODTOK

RO SIFON DE PARDOSEALĂ
PYC ТРАП
BUL ПОДОВ СИФОН


03.05.2016

HL80.2H

0,50 l/sec
DN50/75



9 003076 701827



D BODENABLAUF
I SCARICO A PAVIMENTO
GB FLOOR DRAIN

TR YER SÜZGEÇİ
CZ/SK PODLAHOVÁ VPUST
HR PODNI ODVOD




H PADLÓLEFOLYÓ
PL WPUST PODLOGOWY
SLO TALNI ODTOK

RO SIFON DE PARDOSEALĂ
PYC ТРАП
BUL ПОДОВ СИФОН


03.05.2016

HL80.2H

0,50 l/sec
DN50/75



9 003076 701827



D BODENABLAUF
I SCARICO A PAVIMENTO
GB FLOOR DRAIN

TR YER SÜZGEÇİ
CZ/SK PODLAHOVÁ VPUST
HR PODNI ODVOD

H PADLÓLEFOLYÓ
PL WPUST PODLOGOWY
SLO TALNI ODTOK

RO SIFON DE PARDOSEALĂ
PYC ТРАП
BUL ПОДОВ СИФОН

03.05.2016